

October 22, 2009

Mr. Carven Blanck
Muza Sheet Metal Company, LLC
51 W. Fernau Avenue
Oshkosh, WI 54901

Dear Carven:

On Monday, October 19, 2009, Integrated Risk Management Associates, LLC did a field inspection at the Georgia-Pacific Plant on South Broadway Street in Green Bay, Wisconsin. Our report and recommendations follow:

I arrived on-site at 1:00 pm. Eric Olson is journeyman in charge supervising five other Muza employees. Employees are installing new wall panels to the outside of the building. All Muza employees were wearing harnesses and retractable lifelines. Georgia-Pacific safety rules mandate retractable lifelines for all work over 4 feet. All Muza employees were also wearing leather gloves, as Georgia-Pacific also requires gloves for all sheet metal workers to help prevent infection from cuts.

Georgia-Pacific, Selmer Construction, and the roofing contractor all have safety people on-site; therefore, the work is well observed.


On Friday, October 16th, Selmer Construction lifted all of Muza's equipment and materials onto the roof, thereby limiting the number of trips down from the roof level.

Muza has two scaffolds assembled on the roof. Both were fully planked, and locked in place.

No discrepancies were found.

I departed the site at 1:45 pm.

Sincerely,



Charles P. Howes
Senior Safety Engineer
Integrated Risk Management Associates, LLC



Photo 1



Photo 2