

June 30, 2009

Mr. Carven Blanck
Muza Sheet Metal Company, LLC
51 W. Fernau Avenue
Oshkosh, WI 54901

Dear Carven:

On Wednesday, June 24, 2009, Integrated Risk Management Associates, LLC did a field inspection at Wal-Mart in Kenosha, Wisconsin. Our report and recommendations follow:

Wal-Mart, 6414 38th Street, Kenosha, WI

I arrived at the Wal-Mart jobsite at about 10:30 am. I signed in and talked to the general contractor, Don Malin, of Carlson Brothers, Inc. Don expressed interest to see that Muza had a safety inspector, and we exchanged cards. Don said that he had no safety concerns with the Muza crew, but did express a concern that we did not have enough people on site.

I observed three Muza trucks and six Muza employees on site. All three trucks (10, 14, and 16) were equipped with First Aid Kits and drinking water. Temperatures were in the high 80's or 90's and very humid.

Eric Bertrand and three employees were working on a steep pitch roof on the South side of the building (Photos 1 & 2), and Travis and another employee were working on an overhang in the center of the building (Photos 3 & 4). Two sections of scaffolding (10 feet) were installed on the roofs of both locations. Scaffolds were on casters resting on plywood bases. An eight foot parapet to a flat roof surrounded each of the scaffold assemblies.

Employees working on the steep-slope roof were properly harnessed, and had both a grab-line and chicken ladder properly installed.

Three Ariel-lifts were present: DL2198, D353, and D357. All appeared to be in good working order and had manuals. Muza employees were properly harnessed and tied-off while operating the lifts.

Eric told me that OSHA had been there the week before and cited some carpenters.

It was extremely hot and dry. I reminded all employees to stay hydrated.

No discrepancies found. I departed from the site at 12 noon.

I would suggest that, if additional personnel are added to this site, that we check it out again.

Sincerely,

Charles

Charles P. Howes

Senior Safety Engineer

Integrated Risk Management, LLC

CH/kb



Photo 1



Photo 2



Photo 3



Photo 4